Survey No. AA859

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

1. Nam	le (indicate pr	referred name)		
historic W	ATKINS/WELSH WING			
and/or common	WATKINS/WELSH	SCHOOLHOUSE		
2. Loca	ation			
street & number	DAVIDSONVI	LLE ROAD		not for publication
city, town	DAVIDSONVILLE	vicinity of	_{1է} բongressional district	
state	MARYLAND	county	ANNE ARUNDEL	co.
3. Clas	sification			
Category districtx building(s) structure site object	Ownership publicxprivate both Public Acquisition in process being consideredxnot applicable	Status X occupied unoccupied work in progress Accessible X yes: restricted yes: unrestricted no	Present Use agriculture commercial _X_ educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names an	nd mailing addresses	s of <u>all</u> owners)
name RO	OBERT A GAUG	,		
street & number	1478 ST STEPHEN	IS CHURCH ROAD	telephone no) .:
city, town	CROWNSVILLE MD	state	and zip code	21032
5. Loca	ation of Leg	al Description	n	
courthouse, regi	stry of deeds, etc.	ANNE ARUNDEL COUNT	Y COURTHOUSE	liber ²⁸⁵⁴
street & number	SOUTH	STREET		folio 614
city, town	ANNAPOLIS		state	MD 21401
6. Rep	resentation	in Existing	Historical Surve	eys
itle				
late			federai state	county ioca
pository for su	arvey records			
city, town			atata	
	·· . •		state	

	7.	Des	cript	ion
--	-----------	-----	-------	-----

Survey No. AA-859

Condition excellentgood	deteriorated ruins	Check one unalteredxaltered	Check one original six moved	ite date of move	
fair	unexposed				

Prepare both a summary paragraph and a general description of the resource and its

various elements as it exists today.

This small building faces south and is now located off Old
Davidsonville Road. It is north of route 424 and west of route 50
approximately one-half mile from the intersection of these two roads.
It is visible from both routes. The structure was moved to its present location on a level field when route 50 was built.

The original section of this building was once a one room schoolhouse. It had been built by the Welsh and Watkin's families to house the tutoring of Benjamin Watkins II and Ann Welsh who were later married. It's original location was on the south side of Route 424 in a field to the left of the current road to the farm of Benjamin Watkins IV. The two families hired a schoolmaster named Hefferman. He was given room and board with the Welshes and a salary of \$70 per year. Upon his suicide the school was abandoned as such and was moved to the vicinity of Route 50 near the present site. A kitchen wing was added and the building was converted to house the manager of the Watkins farm. When Route 50 was constructed this building had to be moved. The original school section had deteriorated so greatly that it was removed. It is only the kitchen addition that survives.

This one and half story building has a gable roof which has been extended on the front to cover a full width porch. Closer inspection reveals that a narrowerer centered porch roof still remains under the newer roof. The original two square posts of this earlier roof supports the current roof with another one at the west end. The west side has been enclosed. The floor is concrete. A front entrance is centered. Its door has six panes over a single panel. To the right is a narrow vertical single pane window.

The east side has a cinder block chimney centered in the gable. There are no first floor windows. In the gable, flanking the chimney, are a pair of four pane outswinging windows.

The rear of the house has only one two over two horizontal pane window slightly to the left of center.

On the west side are two similar two over two windows centered one on each level.

The front of the house has siding of painted particle board. The rest of the siding is asbestos. The roof is asphalt shingles. The only observable feature of the original building is rough weathered box cornice and frieze board on the rear with similar wood used for rake boards on the gable eaves. The later widen at the ends. The foundation is cinder block. It was not possible to observe the sills, joists, & rafters.

To the northeast is a shed roof necessary with board and batten siding.

Southwest of the house is a hand pump set in concrete, on the pum is the manufacturers name; McDonald Mfg Co. Fig 706.

<u>o.</u> 3	Dignificance	Survey No.	AA-859
Period	Harming Harmin	J landscape architecture law literature military music	science sculpture social/ humanitarian theater
Specific	dates Builder/Architect		
check:	Applicable Criteria: A B C D and/or Applicable Exception: A B C D	_EFG	
	Level of Significance:nationalstate	local	
Prepare support	both a summary paragraph of significance and	a general statement o	of history and

9. Major Bibliographical References

10. Ge	ograph	ical Data	<u>-</u>		
Quadrangle nam	e	nplete UTM refer		Quadrang	le scale
Zone Eastin	ng N	orthing	B Zone E	asting	Northing
C			D		
		and justification		nty houndaries	
			lapping state or cou	nty boundaries	code
List all states		for properties over		nty boundaries	_
List all states state state	and counties	for properties over	county	nty boundaries	code
List all states state 11. FOI	and counties	for properties over code code	county	nty boundaries	code
List all states state state 11. For name/title	and counties or many many memory and many memory me	code code	county		code
List all states state state 11. For name/title	and counties TM Prepaying a videonville	code code code survey TEAM	county COUNTY	a 3/85	code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438



South